

Klarman, Steven C

From: Klarman, Steven C
Sent: Tuesday, July 21, 2009 12:19 PM
To: Derrington, Bill ; Freed, Steven T
Cc: Leskowitz, Mark A ; Trunk, John W ; Lawhon, Charles M
Subject: #5 Boiler PCB Sample Results

Attachments: #5 Boiler PCB Soil Samples.pdf

Clean Harbors took three soil samples in the proposed location for #5 Boiler on 7/17/09. The samples were collected from 0-4 ft below ground surface using direct push (Geoprobe) core sampling equipment. The results were all Non-Detect for PCBs. Laboratory reports and a drawing showing the sample locations are attached.



#5 Boiler PCB Soil
Samples.pdf...

Steve

AC & S, Incorporated

Serving the chemical industry since 1986

Specialty Chemical - Laboratory Services - Rail Tank Cleaning

Report of Analysis

Name: Clean Harbor Environmental Services
Teresa Wasson
414 Goff Mountain Road
Cross Lanes, WV 25313
Sample Date: 7/17/2009 11:30
Receipt Date: 7/17/2009 14:22
Report Date: 7/20/2009

Sample ID#: 09972788
Sample Source: (None)
BHI 0-4
Client Sample MPM Silicones LLC

Parameter	Sample Result	Units	MDL	Analysis Start	Analysis End (If Applicable)	Method	Analyst
PCB's							
Aroclor 1016	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1221	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1232	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1242	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1248	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1254	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF
Aroclor 1260	ND	mg/kg	0.05	07/18/09 23:30		SW 8082	LKF

Reviewed by:

Priscilla Vassar

AC&S, Inc.
P.O. Box 335
Nitro, WV 25143

ND = Not Detected
* = Above Specified Limit

Note: The test results are only valid for date sample was taken. We do not accept any liability for use of these results.

Page 1 of 33

SISVIL012125

EPA004246

AC & S, Incorporated

Serving the chemical industry since 1986

Specialty Chemical - Laboratory Services - Rail Tank Cleaning

Report of Analysis

Name: Clean Harbor Environmental Services
Teresa Wasson
414 Goff Mountain Road
Cross Lanes, WV 25313
Sample Date: 7/17/2009 11:30
Receipt Date: 7/17/2009 14:22
Report Date: 7/20/2009

Sample ID#: 09972789
Sample Source: (None)
BH2 0-4
Client Sample MPM Silicones LLC

Parameter	Sample Result	Units	MDL	Analysis Start	Analysis End (If Applicable)	Method	Analyst
PCB's							
Aroclor 1016	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1221	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1232	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1242	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1248	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1254	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF
Aroclor 1260	ND	mg/kg	0.05	07/19/09 0:07		SW 8082	LKF

Reviewed by:

Priscilla Vassar

AC&S, Inc.
P.O. Box 335
Nitro, WV 25143

ND = Not Detected
* = Above Specified Limit

Note: The test results are only valid for date sample was taken. We do not accept any liability for use of these results.

Page 2 of 33

SISVIL012126

EPA004247

AC & S, Incorporated

Serving the chemical industry since 1986

Specialty Chemical - Laboratory Services - Rail Tank Cleaning

Report of Analysis

Name: Clean Harbor Environmental Services
Teresa Wasson
414 Goff Mountain Road
Cross Lanes, WV 25313
Sample Date: 7/17/2009 11:30
Receipt Date: 7/17/2009 14:22
Report Date: 7/20/2009

Sample ID#: 09972790
Sample Source: (None)
BH3 0-4
Client Sample MPM Silicones LLC

Parameter	Sample Result	Units	MDL	Analysis Start	Analysis End (If Applicable)	Method	Analyst
PCB's							
Aroclor 1016	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1221	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1232	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1242	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1248	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1254	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF
Aroclor 1260	ND	mg/kg	0.05	07/19/09 0:43		SW 8082	LKF

Reviewed by:

Priscilla Vassar

AC&S, Inc.
P.O. Box 335
Nitro, WV 25143


ND = Not Detected
* = Above Specified Limit

Note: The test results are only valid for date sample was taken. We do not accept any liability for use of these results.

Page 3 of 33

SISVIL012127

EPA004248



SISVIL012128

EPA004249